Pre-Purchase Inspection				359	sic	: Automobilia			
Report No		-			04	25 250 613 Auction Lot No			
		I	Main	tenar	nce, I	Addifications & Restorations 21			
		ABN:	95 933	3 498 1	716	MVRL 38236			
				J - J O /		Image: An and the second sec			
Inspection Date					Make/M	odel Year Odometer - VIN MIs / Km	Rating	; /5 <mark>3.5</mark>	
45406				Fo	ord Mu	stang 1966 44,154mls 6F07C361275	All values will be rou	inded down to the nearest	0.5
		Ove	erall Rat	ting		Comments			
	1	1	1	0.5	0	Nice vehicle that needs a few repairs to make a very good car.			
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments	Type 'a	' for ticks	
Presentation	✓								
Glass									
Bodywork						Blistering at base of doors.			
Paintwork									
Lamps Condition	✓ ✓								
Bumper Bars Brightwork									
Seals									
Convertible Roof	•				~				
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments			
Boot Area	✓								
Seats & Belts	·								
Floor Coverings	✓								
Headlining/Visors	✓								
Trim	✓								
Doors	✓								
Windows and Mirrors	✓								
Heating and Ventilation	✓								
Lights/Wipers/Washers/Horn	 ✓ 								
Other Electrical	✓								
Entertainment Equipment	 Image: A start of the start of								
ABS/SRS					✓				
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments			
Structure Corrosion		 				Evidence of floor panels being replaced. Patch repair on L/H/R chassis rail. Advanced surface corrosion on chassis rails.			
Powertrain	✓	•							
Exhaust	✓								
Brakes			✓			Brake fluid leaking from rear drums.			
Wheels & Tyres	✓								
Steering & Suspension	 ✓ 								
Fuel System		✓				Sender unit weeping.			
Fluid Leaks						Final drive leaking badly. Oil drips from transmission bell housing.			
						Pge 1/2			
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments			
Presentation									
Fluid Levels/Condition		4							
Cooling System		✓				Coolant brown.			
	✔								
Power Steering Electrical						Idles fast.			
Electrical	✓ ✓				1	Refrigerant depleted.			
	>		✓						
Electrical Engine Running Air Conditioning	·	Fair	✓ Repair	N/C	N/A	Comments			
Electrical Engine Running Air Conditioning ROAD TEST	¥	Fair		N/C					
Electrical Engine Running Air Conditioning ROAD TEST Engine Performance	Good	Fair		N/C					
Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Transmission	Good	Fair		N/C					
Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration	Good	Fair		N/C					
Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension	Good	Fair		N/C	N/A		Image: Constraint of the second se		
Electrical Engine Running	Good			N/C	N/A	Comments	Image: Constraint of the second se		
Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension Braking	Good			N/C	N/A	Comments			

							Кеу													
Good	Operat	ional or w	vell pres	sented a	at time	of inspe	ction						U/S	U	nservicable					
Fair														N	ot secure					
Repair	RepairRequires repair, replacement or refurbishmentWettingFluid escaping with the potential to drip \overleftrightarrow \overleftrightarrow \overleftrightarrow \overleftrightarrow \checkmark \overleftrightarrow \checkmark \overleftrightarrow \checkmark \overleftrightarrow \checkmark \overleftrightarrow \checkmark <tr< th=""><th>N</th><th>ot working</th><th></th><th></th><th></th><th></th><th></th></tr<>													N	ot working					
	Fluid e	scaping w	ith the	potenti	ial to dri	р							N/A	N	ot Applicable	1				
	Fluid e	scaping a	nd dripp	oing									N/C	N	ot checked					
$- \bigstar \bigstar & \updownarrow & \swarrow & & \\ - \bigstar & \bigstar & \bigstar & & & \\ - \bigstar & \bigstar & & & & & & \\ \end{array}$	$ \begin{array}{c} \star & \star & \star \\ \star & \star & \star \\ \star & \star & \star \\ \end{array} \end{array} $ Vehicle requires substantial work or restoration $ \begin{array}{c} & \\ & \\ & \\ & \\ & \\ & \\ & \\ & \\ & \\ & $																			
$\star \star \star \star \star \star$ Vehicle is in poor condition and in need of TLC Vehicle is commonsurate with age and useable																				
	Wetting Fluid escaping with the potential to drip N/A Not Applicable \therefore \widehat{x} <td< th=""><th></th><th></th><th></th><th></th><th></th></td<>																			
						Di	eclaim	or												
This is a visual inspection only ca conclusively diagnosed. F						8236). N	lo com	ponents												
Classic Automobilia (MVRL382	36) will n	ot be held	d liable	or respo		in regar purcha			(s) in re	elatio	on to this	s rep	ort or any imp	olied	influence to your decision to					
The following items are not i	ncluded	in this i	nspect	ion rej	port : -	-	e Comp Iponei		ons, ins	spec	tion of	Can	n/Timing Be	elt(s)	or any internal mechanical					
This pre-purchase inspection	report is	not a sub	ostitute	for a ro	adwort	hy certif	icate ar	nd in no	way im	nplies	s the vel	hicle	will or will no	t pas	s a roadworthy inspection.					
															Pge 2/2					
										_	_						 	 		

										(

##