					- :-	- A. I.									
Pre-Purchase Inspection						Autom	OOME	* 							
Report No		04			04	25 250 613			Auction Lot No						
		Maintenance, I				Modifications & Restorations			Lot 29						
		ABN:	95 933	498 7	716	MVRL 38236									
Inspection Date					Make/N	ladal	Year	Odometer -	VIN						
		Mercedes-E				MIS / KM					Ra	ating ,	/5	4.0	
2/8/24											All values w	vill be round	led down to	the nearest 0.	5
		Ove	rall Ra	ting		Comments									
	1	1	1	1	0	A good re	estoration that	needs some fin	ishing touches.						
EVTERIOR	04	Fair	Domeiu	N/C	N/A						T		fan L		
Presentation	Good	rair	Repair	IN/C	IVA			omments			ιyρ	be a	for ti	CKS	
Glass	y														
Bodywork	·	~				Some poor panel fitment an	nd gaps. Some rip	pling in side pane	els.						
Paintwork	>	•				Has some blemishes in the p		h0 e.e.e he							
Lamps Condition	~														
Bumper Bars	>														
Brightwork	>														
Seals	✓														
Convertible Roof					~										
INTERIOR	Good	Fair	Repair	N/C	N/A		С	omments							
Boot Area	~														
Seats & Belts	>														
Floor Coverings	>														
Headlining/Visors	~														
Trim	✓					L/H underdash trim falling d	lown.								
Doors	>					Tops of door trims faded and	d splitting in plac	es.							
Windows and Mirrors	~														
Heating and Ventilation			~			Control levers not working.	A/con N/W.								
Lights/Wipers/Washers/Horn	>			_		Wipers do not park.									
Other Electrical				>											
Entertainment Equipment			~			N/W.									
ABS/SRS	Cood	Foir	Donois	N/C	N/A			ommonto.							
UNDERBODY Structure	Good	Fair	Repair	N/C	IV/A			omments							
Corrosion	>					Evidence of several patch pa	anel repairs.								
Powertrain	>														
Exhaust			✓			Engine pipe leaking.									
Brakes	>														
Wheels & Tyres	~														
Steering & Suspension	~					Aged but serviceable.									
Fuel System	~		~			Fuel tank drain bung leaking	3 .								
Fluid Leaks		✓				Final drive and transmission	leaking. Engine	wet.							
									Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A		С	omments							
Presentation	✓														
Fluid Levels/Condition	>														
Cooling System	~		4												
Power Steering	4		>			Pump and box leaking.									
Electrical															
Engine Running Air Conditioning	>		y			Not working, suspect refrige	arant deploted								
ROAD TEST	Good	Fair	·	N/C		Not working, suspect reinige		omments							
	Jour	ı all		14/0		Lacks nower and noor trans			tor linkages not giving full throttle						
Transmission			•				on operatio	. age to acceler di							
Noise and Vibration		•				355 48646.									
Steering and Suspension															
Braking	>														
Clutch					~										
Instruments	>														
	Lacks power and poor transmission operation due to accelerator linkages not gives smission e and Vibration ring and Suspension ing ch														

		Key								
Good Fair Repair Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia Vehicle is in poor condition Vehicle is commensurate w Vehicle is in very good cond	I work or restoration and in need of TLC rith age and useable								
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed. Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (nderbody was visually in	and any faults listed have not been spected on a vehicle hoist. ed influence to your decision to estate the spected of the spected on a vehicle hoist.				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.										