				I	1							
Pre-Purchase Inspection		4	Cla	959	sic	: Automobilia						
Report No					04	25 250 613 Auction Lot No						
		-	Main	<b>.</b>								
		_	Main	tenar	ice, r	Modifications & Restorations Lot 31						
		ABN:	95 933	3 498	716	MVRL 38236						
						odel Veer Odometer - VIN						
Inspection Date				I	Make/N	odel Year Odoffieter - VIN		Ra	ating /	5	4.0	
2/8/24				Isu	zu Bell	ett GTR 1969 85,399km PR914209893		All values w	vill be rounded	d down to t	he nearest 0.5	
		Ove	roll Do	ting		Commente						
			erall Rat	ung		Comments						
	1	1	1	1	0	Vehicle has received significant investment but needs a bit more to finish.						
								_				
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments		Typ	e 'a' f	or tic	cks	
Presentation	<b>✓</b>											
Glass	<b>✓</b>											
Bodywork	<b>✓</b>					Poor panel fit, notably the bonnet and boot.						
Paintwork	<b>✓</b>											
Lamps Condition	<b>~</b>											
Bumper Bars	<b>~</b>											
Brightwork	<b>~</b>											
Seals	•											
Convertible Roof	<b>-</b>				_							
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments						
Boot Area	<b>~</b>											
Seats & Belts			<b>~</b>			Passenger seat belt N/S.						
Floor Coverings		<b>~</b>										
Headlining/Visors		<b>✓</b>				Some overspray on lining.						
Trim		<b>✓</b>				Poor finish.						
Doors		<b>✓</b>										
Windows and Mirrors		<b>~</b>										
Heating and Ventilation			<b>~</b>			Not working and vent controls not operational.						
Lights/Wipers/Washers/Horn			<b>,</b>			Wipers don't park and need adjusting. Horn N/W. Washers N/W.						
Other Electrical			<b>*</b>			Interior lamp broken.						
	.4		•			interior lamp broken.						
Entertainment Equipment	<b>~</b>				4							
ABS/SRS					<b>✓</b>							
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments						
Structure		<b>✓</b>				Evidence of repairs.						
Corrosion		<b>✓</b>				Some corrosion in secondary structure. Heavy coating of underseal.						
Powertrain		<b>~</b>										
Exhaust	<b>~</b>											
Brakes		<b>✓</b>										
Wheels & Tyres			<b>~</b>			Tyres aged.						
Steering & Suspension		<b>✓</b>				Aged and worn.						
Fuel System	<b>~</b>											
Fluid Leaks	<b>✓</b>											
						Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments						
			nopun	100	1071							
Presentation  Fluid Levels/Condition	<b>V</b>											
Fluid Levels/Condition	<b>V</b>											
Cooling System	<b>~</b>											
Power Steering					~							
Electrical	<b>~</b>											
Engine Running	~											
Air Conditioning					<b>~</b>							
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments						
Engine Performance	<b>~</b>											
Transmission		<b>✓</b>				Poor gate/selector.						
Noise and Vibration			<b>✓</b>			Grinding noise in final drive.						
Steering and Suspension			•			Excessive play in steering and pulls.						
Braking		<b>V</b>	·			. ,						
Clutch		▼										
	<b>~</b>		. 4			Temp gauge N/W and some warning lamps						
Instruments			<b>~</b>			Temp gauge N/W and some warning lamps.						
						General Comments						
							_					

		Key								
Good Fair Repair  Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia  Vehicle is in poor condition  Vehicle is commensurate w  Vehicle is in very good cond									
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed.  Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (	nderbody was visually in	and any faults listed have not been spected on a vehicle hoist.  ed influence to your decision to  e(s) or any internal mechanica				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.  Pge 2/2										