					_ • _												
Pre-Purchase Inspection		04				= Automobilia											
Report No						25 250 613		Auction Lot No									
						Modifications & Restorations			Lot 34								
		ARNI	95 933	100	716		MVRL 38236										
		ADIN.	33 33 3	430	/10												
Inspection Date					Make/N	lodel	VASIC	ometer - s / Km	VIN	Rating /5 3.0							
2/8/24		MGB GT Overall Rating				Coupe 1971 35,213mls GDB058166P					All values w	vill be round	II be rounded down to the nearest 0.5				
		Ovo	roll Dat	ting			Comme	nto									
	1	1	1	0	0	Good drivetrain and struc	ture, could use	some bo	dywork & cosmetic work.								
EXTERIOR	Good	Fair	Repair	N/C	N/A		Commer	ıts			Tyr	יב' פר	for ti	rks			
Presentation	0.000	✓			1 1 1 1						' ' ' ' '	oc a	וטו נו	CKS			
Glass		>									_						
Bodywork		•	>			Corrosion in several areas and som	ne poor shaping.	Evidence o	f several repairs. Several dings.								
Paintwork			•			Corrosion blisters in areas.	1 1 0		, c								
Lamps Condition		>															
Bumper Bars		>				Badly tarnished.											
Brightwork		>				Grill dented.											
Seals		>															
Convertible Roof					~												
INTERIOR	Good	Fair	Repair	N/C	N/A		Commer	its									
Boot Area		~															
Seats & Belts		>															
Floor Coverings		>															
Headlining/Visors			✓			Aged and untidy.											
Trim			✓			Aged and worn, some tears visible											
Doors		>															
Windows and Mirrors		>				Cracked and tarnished.											
Heating and Ventilation																	
Lights/Wipers/Washers/Horn			✓			L/H headlamp N/W.											
Other Electrical				✓													
Entertainment Equipment	✓																
ABS/SRS					~												
UNDERBODY	Good	Fair	Repair	N/C	N/A		Commer	its									
Structure	~																
Corrosion	V																
Powertrain	V	>				Badly dented.											
Exhaust Brakes	~	•				Bauly defited.											
Wheels & Tyres	,																
Steering & Suspension	V																
Fuel System	~																
Fluid Leaks	~					Transmission and engine wet											
									Pge 1/2								
ENGINE BAY	Good	Fair	Repair	N/C	N/A		Commer	ıts									
Presentation		✓	-														
Fluid Levels/Condition	~																
Cooling System	✓																
Power Steering					~												
Electrical		>				Untidy.											
Engine Running	✓																
Air Conditioning					~												
ROAD TEST	Good	Fair	Repair	N/C	N/A		Commer	its									
Engine Performance	✓																
Transmission	✓																
Noise and Vibration	✓																
Steering and Suspension	✓																
Braking	✓																
Clutch	✓																
Instruments		✓															
						General Comments											
General Comments																	
											1						

		Key								
Good Fair Repair Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia Vehicle is in poor condition Vehicle is commensurate w Vehicle is in very good cond	I work or restoration and in need of TLC rith age and useable								
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed. Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (nderbody was visually in	and any faults listed have not been spected on a vehicle hoist. ed influence to your decision to estate the spected of the spected on a vehicle hoist.				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.										