				I	_											
Pre-Purchase Inspection		-		959	Sic	Autor	nobilic	•								
Report No					04	25 250 61	3		Auction Lot No							
			Main	tenar	nce, I	Modifications & Restorations										
			05.023	100	74.6											
		ABN:	95 933	3 498 /	/16		MVRL 38	3236								
Inspection Date				N	Make/N	lodel	Year	Odometer - Mls / Km	VIN		Ra	iting /5	5	2.5		
28/2/25		Ford XB Fa														
												All values will be rounded down to the nearest 0.5				
	Overall Rating Comments															
	1	1	0.5	0	0		Structurally sour	nd and straight v	vehicle.							
											_					
EXTERIOR	Good	Fair	Repair	N/C	N/A		С	omments			Тур	e 'a' f	or tic	ks		
Presentation			<b>✓</b>													
Glass		<b>&gt;</b>														
Bodywork	<b>~</b>		<b>&gt;</b>			and tail lamn nanel	dents and minor dan	nage. Advanced ru	ist at base of rear screen screen							
Paintwork			<b>&gt;</b>			Paint has surface corros	ion evident in variou	s locations.								
Lamps Condition	<b>~</b>															
Bumper Bars		<b>&gt;</b>				Tarnished. Rear over ric	er not secure.									
Brightwork		<b>✓</b>														
Seals			<b>&gt;</b>													
Convertible Roof					~											
INTERIOR	Good	Fair	Repair	N/C	N/A		С	omments								
Boot Area			<			Tail lamp panel and boo	t gutter below screer	rusted out.								
Seats & Belts		<b>~</b>				Aged, soiled and front s	eat badly torn. Seat b	oelts U/S.								
Floor Coverings		<b>~</b>				Aged and soiled.										
Headlining/Visors		<b>✓</b>				Aged and soiled.										
Trim		<b>✓</b>				Aged and soiled.										
Doors		<b>✓</b>				Door internal and exter	nal furniture corrode	d/tarnished.								
Windows and Mirrors		<b>~</b>														
Heating and Ventilation				<b>✓</b>												
Lights/Wipers/Washers/Horn				<b>✓</b>												
Other Electrical				<b>✓</b>												
Entertainment Equipment				<b>✓</b>												
ABS/SRS					<b>✓</b>											
UNDERBODY	Good	Fair	Repair	N/C	N/A		С	omments								
Structure	<b>✓</b>															
Corrosion	~															
Powertrain				~												
Exhaust			<b>&gt;</b>													
Brakes				~												
Wheels & Tyres		<b>&gt;</b>		,		Tyres U/S Trims and wh	eels fair.									
Steering & Suspension				<b>V</b>												
Fuel System				<b>V</b>												
Fluid Leaks				~												
									Pge 1/2							
ENGINE BAY	Good	Fair	Repair	N/C	N/A		С	omments								
Presentation		<b>~</b>														
Fluid Levels/Condition			<b>&gt;</b>			Engine oil milky. Brake f	luid depleted.									
Cooling System			<b>✓</b>			Depleted.										
Power Steering					~											
Electrical				<b>✓</b>												
Engine Running				<b>~</b>												
Air Conditioning					<b>✓</b>											
ROAD TEST	Good	Fair	Repair	N/C	N/A		С	omments								
Engine Performance				<b>✓</b>		Engine not started, no r	oad test completed.									
Transmission				<b>~</b>												
Noise and Vibration				<b>✓</b>												
Steering and Suspension				<b>✓</b>												
Braking				<b>✓</b>												
Clutch				<b>~</b>												
Instruments				<b>✓</b>												
						Conord Committee										
						General Comments										

		Key								
Good Fair Repair  Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia  Vehicle is in poor condition  Vehicle is commensurate w  Vehicle is in very good cond									
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed.  Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (	nderbody was visually in	and any faults listed have not been spected on a vehicle hoist.  ed influence to your decision to estate the spected of the spected on a vehicle hoist.				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.										