				I	_										
Pre-Purchase Inspection			Classic Automobilia												
Report No					04	Auction Lot No Auction Lot No									
		Maintenance,				Modifications & Restorations									
			05.023	100	74.6		1.0VD1.00								
		ABN:	95 933	3 498 /	116		IVIVRL 38	236							
Inspection Date				N	Make/M	lodel	Rating /5 3.0								
28/2/25		Holden HQ N													
		Ove	rall Ra	ting											
	1	1	1	0	0		Solid rus	t free example.							
											T	- 1-14	C + •	_	
EXTERIOR	Good	Fair	Repair	N/C	N/A			omments			тур	e a 1	ror π	CKS	
Presentation			~			Vehicle is generally aged a	and soiled.								
Glass		>													
Bodywork	~	4													
Paintwork	. 4	>				Average paint finish with j	poor attention to b	ackout sections.							
Lamps Condition	V					Tauniahad									
Bumper Bars	V					rarnisned.									
Brightwork Seals		>				I /H nllarless soal missing									
Convertible Roof		▼			✓	בין דו טוומווכטט טבמו ווווטטוווץ.									
INTERIOR	Good	Fair	Repair	N/C	N/A		^	Ommente							
	G000		nepair	IV/C	N/A		C	omments							
Boot Area		>				Spate good halts are see									
Seats & Belts Floor Coverings		>				acara good beits are aged									
Headlining/Visors		>				Visors distorted									
Trim															
Doors						Solieu aliu ageu.									
Windows and Mirrors															
Heating and Ventilation															
Lights/Wipers/Washers/Horn															
Other Electrical															
Entertainment Equipment				,	_										
ABS/SRS					~										
UNDERBODY	Good	Fair	Repair	N/C	N/A		С	omments							
Structure	✓					Vehicle could not be put of	on hoist so inspection	on was visual from	ground level.						
Corrosion	✓														
Powertrain				✓											
Exhaust				~											
Brakes				~											
Wheels & Tyres			>				S.								
Steering & Suspension						Appears good but aged.									
Fuel System															
Fluid Leaks															
									Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A		С	omments							
Presentation		~													
Fluid Levels/Condition	✓		,												
Cooling System			>			Depleted.									
Power Steering															
Electrical															
Engine Running				V		Engine turns but not start	ea.								
Air Conditioning	Casi	Fa!	Den :	AL/O				ommorts.							
ROAD TEST	GOOD	rair	nepair		n/A		С	omments							
Engine Performance Transmission				·											
Noise and Vibration															
Steering and Suspension															
Braking															
Clutch						Auction Lot 160 Notice of the Comments Auction Lot 160 Notice of the Comments Auction Lot 160 Comments Solid rust Tree example. Comments Type 'a' for ticks Type 'a' for ticks Type 'a' for ticks Lift address and make a granding age and acids. Lift address and make a granding age and acids. Lift address and make a granding age and acids. Lift address and make a granding age and acids. Comments Comments Comments									
Instruments				•		Appear to be in good con	dition.								
	Soiled and aged. Ventilation Soiled and aged. Ventilation It Equipment Order of Fair Repair No NA Comments Wheels poor and tyres U/S. Appears good but aged. Wheels poor and tyres U/S. Appears good but aged. Order of Fair Repair No NA Comments EBAY Good Fair Repair No NA Comments Order of Fair Repair No NA Comments EST Good Fair Repair No NA Comments Appears good but not started. Engine turns but not started. Appear to be in good condition.														

		Key								
Good Fair Repair Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia Vehicle is in poor condition Vehicle is commensurate w Vehicle is in very good cond									
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed. Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (nderbody was visually in	and any faults listed have not been spected on a vehicle hoist. ed influence to your decision to estate the spected of the spected on a vehicle hoist.				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.										