<u></u>			<u> </u>									
Pre-Purchase Inspection		1 (	⊂lc	359	sic	: Automobilia						
Report No					04	25 250 613	Auction Lot No					
Перентно		┨ ,	Moin	tonor		Modifications & Restorations	Addition Lot No					
		_	Viaiii	terrar	100, 1	Additications & Restorations						
		ABN:	95 933	3 498 7	716	MVRL 38236						
Inspection Date				N	/lake/N	odel Year Odomete			Rating /	′5 <mark>3.</mark>	5	
28/2/25	Isetta 300 1961 34,833mls A328971								All values will be rounded down to the nearest 0.5			
		Ove	rall Ra	ting		Comments						
	1	1	1	0.5	0	Older restoration that presents well I	but needs some TLC.					
									<b>-</b>	C 1° -1		
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments			Type 'a'	tor πcκs		
Presentation	<b>~</b>	. 4										
Glass		<b>V</b>				Windscreen scratched.						
Bodywork												
Paintwork	<b>V</b>											
amps Condition  Bumper Bars	<b>Y</b>											
Brightwork	<b>V</b>											
Seals		<b>~</b>										
Convertible Roof	<b>,</b>	•										
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments						
Boot Area			•		<b>V</b>							
Seats & Belts		<b>~</b>			Ť							
Floor Coverings		<b>V</b>										
Headlining/Visors	<b>✓</b>											
Trim		<b>✓</b>										
Doors	<b>✓</b>											
Windows and Mirrors		<b>✓</b>										
Heating and Ventilation					<b>&gt;</b>							
Lights/Wipers/Washers/Horn	<b>✓</b>											
Other Electrical				<b>~</b>								
Entertainment Equipment	<b>✓</b>											
ABS/SRS					<b>~</b>							
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments						
Structure	<b>✓</b>					Only visually checked on ground as unable to put on hoist						
Corrosion	<b>~</b>											
Powertrain		<b>V</b>										
Exhaust Brakes		<b>Y</b>										
Wheels & Tyres			_			Tyres U/S.						
Steering & Suspension		<b>V</b>	•			A lot of play in steering.						
Fuel System		<b>V</b>				Aged and intake hose split.						
Fluid Leaks		<b>~</b>										
							Pge 1/2					
	Good	Fair	Repair	N/C	N/A	Comments						
ENGINE BAY												
		<b>V</b>										
Presentation		<b>✓</b>		<b>✓</b>								
Presentation Fluid Levels/Condition		<b>✓</b>		> >								
Presentation Fluid Levels/Condition Cooling System		<b>✓</b>			<b>&gt;</b>							
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical		<b>✓</b>			<b>y</b>							
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical		<b>✓</b>		<b>&gt;</b>		Not running very well due to stale fuel.						
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running		<b>✓</b>		<b>&gt;</b>		Not running very well due to stale fuel.						
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning	Good	Fair	Repair	<b>&gt;</b>		Not running very well due to stale fuel.  Comments						
Presentation Iluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning ROAD TEST	Good		Repair	<b>&gt;</b>	✓ N/A							
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning ROAD TEST Engine Performance	Good		Repair	y y	✓ N/A	Comments						
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Fransmission	Good		Repair	N/C	✓ N/A	Comments						
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension	Good		Repair	>	✓ N/A	Comments						
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension Braking	Good		Repair	N/C	✓ N/A	Comments						
Presentation Fluid Levels/Condition Cooling System Power Steering Electrical Engine Running Air Conditioning  ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension Braking Clutch	Good		Repair	> > > > > > > > > > > > > > > > > > >	✓ N/A	Comments						
Presentation Fluid Levels/Condition Cooling System Power Steering	Good		Repair	N/C	✓ N/A	Comments						

		Key							
Good Fair Repair  Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked			
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia  Vehicle is in poor condition  Vehicle is commensurate w  Vehicle is in very good cond								
	Vehicle is in excellent cond	ition Disclair	ner						
conclusively diagnosed.  Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (	nderbody was visually in	and any faults listed have not been spected on a vehicle hoist.  ed influence to your decision to estate the spected of the spected on a vehicle hoist.			
This pre-purchase inspection	n report is not a substitute for	a roadworthy certificate	and in no way ii	nplies t	ne vehicle will or will not	pass a roadworthy inspection.			