

Pre-Purchase Inspection		Classic Automobilia	
Report No	0425 250 613		Auction Lot No
		Maintenance, Modifications & Restorations	

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
27/2/25	Porsche 928S	1981	153,138km	WPOZZZ92ZBS840253

Rating /5 **4.0**

All values will be rounded down to the nearest 0.5

Overall Rating					Comments
1	1	1	1	0	Good solid vehicle that needs finishing touches.

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Glass	✓					
Bodywork	✓					
Paintwork	✓					A few chips, scuffs and minor imperfections.
Lamps Condition	✓					R/H/R lamp lens cracked.
Bumper Bars	✓					Rear bar a little misshapen.
Brightwork					✓	
Seals		✓				Tailgate seal torn.
Convertible Roof					✓	

Type 'a' for ticks

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓					
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors		✓				Rear visors puffy.
Trim	✓					Areas are aged. Leather on dashboard cracking.
Doors			✓			Central locking N/W.
Windows and Mirrors			✓			Door mirror mechanisms broken and N/W.
Heating and Ventilation	✓					
Lights/Wipers/Washers/Horn	✓					
Other Electrical	✓					
Entertainment Equipment	✓					
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					Rails and floors dented from jacks.
Corrosion	✓					
Powertrain	✓					
Exhaust	✓					
Brakes	✓					
Wheels & Tyres	✓					
Steering & Suspension		✓				Aged.
Fuel System	✓					
Fluid Leaks		✓				Transmission leaking. Engine wet.

Page 1/2

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Fluid Levels/Condition	✓					
Cooling System	✓					
Power Steering	✓					Fitting leaking on rack.
Electrical	✓					
Engine Running		✓				Runs very rich on warm up and stalls.
Air Conditioning		✓				Compressor leaking.

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓					
Transmission	✓					
Noise and Vibration	✓					
Steering and Suspension			✓			Excess play in steering wheel/column.
Braking	✓					
Clutch					✓	
Instruments	✓					

General Comments

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Key														
-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
★ ☆ ☆ ☆ ☆	Fluid escaping and dripping	N/C	Not checked
★ ★ ☆ ☆ ☆	Vehicle requires substantial work or restoration		
★ ★ ★ ☆ ☆	Vehicle is in poor condition and in need of TLC		
★ ★ ★ ★ ☆	Vehicle is commensurate with age and useable		
★ ★ ★ ★ ★	Vehicle is in very good condition		
	Vehicle is in excellent condition		

Disclaimer														
------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.														
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.														
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.														
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.														
