			1	1								+-	
Pre-Purchase Inspection			⊂lc	<b>3</b> 59	sic	Automobilia							
Report No					04	25 250 613 Auction Lot No							
neport No			N 4 - : - :	4								-	
			Main	tenar	ice, r	Modifications & Restorations 18A							
		ABN:	95 933	3 498 7	716	MVRL 38236							
Inspection Date				1	Make/M	odel Year Odometer - VIN			Dottos	· <b>-</b>	<i>1</i> E	+	
						Mis / Km			Rating /	5	<b>4.5</b>	+	
12/3/25	Porsche 996 Turbo S Cabriolet 2005 41,803km WPOZZZ99Z5S670123								All values will be rounded down to the nea				
		Ove	erall Ra	ting		Comments							
	1	1	1	1	0.5	Very good vehicle with a few items that need attention.							
		_		_								_	
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments			Type 'a'	for tic	cks		
Presentation	<b>&gt;</b>												
Glass	<b>~</b>					Stone chips on windscreen.							
Bodywork	<b>✓</b>					Minor dent on R/H/R arch.							
Paintwork	<b>✓</b>					Paint on R/H/F door/guard has a shadow/blend line. Front paintwork stone chipped.							
amps Condition	<b>✓</b>												
Bumper Bars			~			Front bar poorly painted, damaged and is delaminating in areas.							
Brightwork					<b>✓</b>								
Seals	<b>✓</b>												
Convertible Roof	~												
NTERIOR	Good	Fair	Repair	N/C	N/A	Comments							
Boot Area		<b>~</b>				Plastics and bonnet underside paint scraped from luggage.							
Seats & Belts	~												
Floor Coverings	<b>✓</b>												
Headlining/Visors				~									
rim	<b>✓</b>					Some plastic buttons aged.							
Doors	~					Driver's grab handle scratched.							
Windows and Mirrors	<b>✓</b>												
leating and Ventilation													
ights/Wipers/Washers/Horn	<b>~</b>					Washers N/W.							
Other Electrical	<b>~</b>												
Entertainment Equipment	<b>✓</b>												
ABS/SRS	<b>✓</b>												
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments							
Structure	<b>✓</b>					R/H/F wheel arch plastic broken.							
Corrosion	<b>✓</b>												
Powertrain	<b>✓</b>												
Exhaust	<b>~</b>												
Brakes	<b>✓</b>												
Wheels & Tyres	~					L/H/R wheel scratched.							
Steering & Suspension	<b>~</b>											-	
Fuel System	<b>~</b>											-	
Fluid Leaks	<b>~</b>					R/H Condensor damp.							
						Pge 1/2							
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments							
Presentation	<												
luid Levels/Condition	<b>✓</b>												
Cooling System	<b>✓</b>												
Power Steering	<b>✓</b>												
lectrical	<b>✓</b>												
Engine Running	<b>✓</b>												
Air Conditioning	<b>✓</b>												
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments							
ngine Performance	<												
ransmission	<b>✓</b>												
loise and Vibration	<b>✓</b>												
teering and Suspension	<b>&gt;</b>												
raking	<b>~</b>												
Clutch	<b>~</b>												
			<b>~</b>			Fuel gauge n/w.							
nstruments			_									+	
nstruments						General Comments							

		Key							
Good Fair Repair  Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked			
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia  Vehicle is in poor condition  Vehicle is commensurate w  Vehicle is in very good cond								
	Vehicle is in excellent cond	ition Disclair	ner						
conclusively diagnosed.  Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (	nderbody was visually in	and any faults listed have not been spected on a vehicle hoist.  ed influence to your decision to  e(s) or any internal mechanica			
This pre-purchase inspection	n report is not a substitute for	a roadworthy certificate	and in no way ii	nplies t	ne vehicle will or will not	pass a roadworthy inspection.			