				1			7						
Pre-Purchase Inspection			⊂lc	<b>3</b> 59	sic	Automobilia							
Report No					04	25 250 613	Auction Lot	No					
		- <b> </b>	Main	tenar		Modifications & Restorations	Lot 30						
			QE 021	3 498 7	716	MVRL 38236							
		ADIN.	95 95	436	710								
Inspection Date				I	Make/M		ometer - Is / Km		Rating /5 5.0				
2/8/24	BMW 635 CSI 1986 360,369km 1887165								All values will be rounde	ed down to the neares	t 0.5		
		Ove	rall Ra	tina		Commo	ents						
	1	1	1	1	1								
						Excellent e	ampie.						
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comme	nts		Type 'a'	for ticks			
Presentation	<b>✓</b>												
Glass	<b>✓</b>												
odywork	<b>✓</b>												
Paintwork	<b>~</b>												
amps Condition	<b>✓</b>												
umper Bars	~												
rightwork	<b>~</b>												
eals	<b>✓</b>												
Convertible Roof		_	_		<b>✓</b>								
NTERIOR	Good	Fair	Repair	N/C	N/A	Comme	nts						
Boot Area													
loor Coverings	<b>&gt;</b>												
leadlining/Visors													
rim	<b>V</b>												
Doors	-												
Vindows and Mirrors	•		<b>✓</b>			Rear window operation slow and stick.							
leating and Ventilation	<b>✓</b>												
ights/Wipers/Washers/Horn	<b>✓</b>												
Other Electrical	<b>✓</b>												
Entertainment Equipment	<b>~</b>												
ABS/SRS	<b>✓</b>												
JNDERBODY	Good	Fair	Repair	N/C	N/A	Comme	nts						
Structure	<b>V</b>												
Corrosion	<b>&gt;</b>												
Powertrain Exhaust	<b>-</b>												
Brakes	<b>V</b>												
Wheels & Tyres			~			Rear tyres worn badly on inner edges.							
Steering & Suspension	<b>✓</b>												
Fuel System	<b>✓</b>												
Fluid Leaks	<b>✓</b>					P/steer pump wet. Oil cooler pipes leaking. Engine	wet around timing chain tensione	r.					
							Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comme	nts						
Presentation	<b>✓</b>												
luid Levels/Condition	<b>V</b>												
a alua = CL-													
	· • • • •												
ower Steering	<b>V</b>												
Cooling System  Power Steering  Electrical  Engine Running	•					1		1	1 1	I	1		
ower Steering													
ower Steering lectrical ngine Running ir Conditioning	<b>&gt;</b>	Fair	Repair	N/C	N/A	Comme	nts						
ower Steering lectrical ngine Running ir Conditioning ROAD TEST	<b>&gt; &gt; &gt;</b>	Fair	Repair	N/C	N/A	Comme	nts						
ower Steering lectrical ngine Running ir Conditioning ROAD TEST ngine Performance	✓ ✓ Good	Fair	Repair	N/C	N/A	Comme	nts						
ower Steering lectrical ngine Running ir Conditioning  ROAD TEST ngine Performance ransmission	✓ ✓ Good	Fair	Repair	N/C	N/A	Comme	nts						
ower Steering lectrical ngine Running ir Conditioning ROAD TEST ngine Performance ransmission loise and Vibration	✓ ✓ Good	Fair	Repair	N/C	N/A	Comme	nts						
lectrical Ingine Running In Conditioning ROAD TEST Ingine Performance Iransmission Itoise and Vibration Iteering and Suspension	✓ ✓ Good ✓ ✓	Fair	Repair	N/C	N/A	Comme	nts						
ower Steering lectrical ngine Running	Good  Good	Fair	Repair	N/C	N/A	Comme	nts						
ower Steering lectrical Ingine Running Ir Conditioning ROAD TEST Ingine Performance Iransmission Ioise and Vibration Iteering and Suspension Iraking	Good  Good	Fair	Repair	N/C	•	Comme  Cluster glass cracked.	nts						

		Key							
Good Fair Repair  Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked			
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia  Vehicle is in poor condition  Vehicle is commensurate w  Vehicle is in very good cond								
	Vehicle is in excellent cond	ition Disclair	ner						
conclusively diagnosed.  Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (	nderbody was visually in	and any faults listed have not been spected on a vehicle hoist.  ed influence to your decision to  e(s) or any internal mechanica			
This pre-purchase inspection	n report is not a substitute for	a roadworthy certificate	and in no way ii	nplies t	ne vehicle will or will not	pass a roadworthy inspection.			