

Pre-Purchase Inspection	Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations	Auction Lot No
Report No		Lot 36

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
30/7/24	Ford Sedan	1936	9,453mls	68T51943

Rating /5 **3.5**

All values will be rounded down to 5

Overall Rating					Comments
1	1	1	0.5	0	Good overall condition.

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Glass		✓				Windscreen scratched.
Bodywork		✓				
Paintwork		✓				Paint is dull and thin with overspray on some components.
Lamps Condition	✓					
Bumper Bars	✓					
Brightwork		✓				Radiator grille poor.
Seals		✓				
Convertible Roof					✓	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓					One boot latch N/W.
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim	✓					
Doors	✓		✓			Driver's door latch poor.
Windows and Mirrors	✓					
Heating and Ventilation					✓	
Lights/Wipers/Washers/Horn		✓				
Other Electrical				✓		
Entertainment Equipment					✓	
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					
Corrosion		✓				Evidence of some areas of corrosion and repairs to floors.
Powertrain		✓				
Exhaust			✓			Engine pipes U/S and leaking.
Brakes		✓				
Wheels & Tyres	✓					
Steering & Suspension			✓			Aged and worn.
Fuel System	✓					
Fluid Leaks	✓					Transmission leaking.

Page 1/2

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Fluid Levels/Condition	✓					
Cooling System	✓					
Power Steering					✓	
Electrical	✓					
Engine Running	✓		✓			Throttle sticks.
Air Conditioning						

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓					
Transmission	✓					
Noise and Vibration	✓					
Steering and Suspension			✓			Steering operation poor and jams when turning.
Braking		✓				
Clutch		✓				Judders a little.
Instruments		✓				Several gauges N/W.

General Comments

Type 'a' for ticks

