					_ •			•••								
Pre-Purchase Inspection		04				- AUTOMODIIIA										
Report No						25 250 613				Auction Lot No						
						Modifications & Restorations				Lot 37						
		A D NI	0E 022	100	716			M//DI 202	26							
		ADIN.	33 33 3	430	/10			IVIVIL 382								
Inspection Date						odel Year Odometer - VIN MIs / Km					Rating /5 4.0					
2/8/24		Ford Gala														1.5
		Ovo	roll Do	ting		Comments										
			erall Rat													
	1	1	1	1	0	,	Very good veh	nicle that j	ust needs finis	hing touches.						
EXTERIOR	Good	Fair	Repair	N/C	N/A			Coi	nments			Tyr	יב' פו	for ti	rks	
Presentation	✓	- 4	110									' ' ' ' '	oc a	וטו נו	CKS	
Glass		>				Scratch in windscre	en.					-				
Bodywork	~							ance N/S. Sn	nall blister on L/	H/R arch.						
Paintwork																
Lamps Condition	•					·										
Bumper Bars	~															
Brightwork	~															
Seals		~														
Convertible Roof					~											
INTERIOR	Good	Fair	Repair	N/C	N/A			Coi	nments							
Boot Area		✓				Poor carpeting.										
Seats & Belts	~															
Floor Coverings	✓															
Headlining/Visors	✓															
Trim	~					Needs a few finishi	ng touches. Adh	hesive runs (evident on some	trim and seating.						
Doors	~															
Windows and Mirrors			✓			Rear view mirror m	issing. Quarter	windows N	W.							
Heating and Ventilation	✓															
Lights/Wipers/Washers/Horn	 •															
Other Electrical	~															
Entertainment Equipment	~															
ABS/SRS					~											
UNDERBODY	Good	Fair	Repair	N/C	N/A			Со	mments							
Structure	~															
Corrosion	V															
Powertrain Exhaust	Y					Radly dented										
Brakes						badiy dented.										
Wheels & Tyres																
Steering & Suspension	·		✓			Front upper contro	l arm bushes m	etal to meta	ıl & several bush	es perished.						
Fuel System	✓		✓			Fuel smell in boot.										
Fluid Leaks					A white fact is places and some gluenuse restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ restant around baseline. Very cool or parel fit. Front Lapter or place russ russ restant around baseline. Very cool or parel fit. Front Lapter or place russ russ russ russ russ russ russ rus											
										Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A		1	Coi	nments							
Presentation	✓															
Fluid Levels/Condition	•															
Cooling System	•															
Power Steering	~					Power steering box	wet.									
Electrical			✓													
Engine Running	✓															
Air Conditioning	~															
ROAD TEST	Good	Fair	Repair	N/C	N/A			Со	nments							
Engine Performance	✓															
Transmission	~		~			Gear selector misal	igned.									
Noise and Vibration			✓			Creaks and groans	from front and r	rear.								
Steering and Suspension			✓			Front suspension b	ushes creak.									
Braking	~															
Clutch					~											
Instruments	✓															
						Conoral Comme	te									
						General Commen	13									
													I.			

		Key								
Good Fair Repair Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia Vehicle is in poor condition Vehicle is commensurate w Vehicle is in very good cond	I work or restoration and in need of TLC rith age and useable								
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed. Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (nderbody was visually in	and any faults listed have not been spected on a vehicle hoist. ed influence to your decision to estate the spected of the spected on a vehicle hoist.				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection. Pge 2/2										