

Pre-Purchase Inspection	Classic Automobilia	
Report No	0425 250 613	Auction Lot No
	Maintenance, Modifications & Restorations	Lot 35

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
2/8/24	Ford Mustang Convertible	1969	8,763	9T03L117162

Rating /5 **5.0**

All values will be rounded down to the nearest 0.5

Overall Rating					Comments
1	1	1	1	1	Superb example and difficult to fault.

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Glass	✓					
Bodywork	✓					Poor boot lid fit.
Paintwork	✓					Blemishes from paint prep in areas. Filler cracking on L/H/R arch. Some chips.
Lamps Condition	✓					
Bumper Bars	✓					
Brightwork	✓					
Seals	✓					
Convertible Roof	✓					

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓					
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim	✓					
Doors	✓					
Windows and Mirrors	✓					
Heating and Ventilation	✓					
Lights/Wipers/Washers/Horn	✓					Washers N/W.
Other Electrical	✓					Gear illumination N/W.
Entertainment Equipment				✓		N/W.
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					
Corrosion	✓					
Powertrain	✓					
Exhaust	✓					
Brakes	✓					
Wheels & Tyres	✓					Aged tyres.
Steering & Suspension	✓					
Fuel System	✓					
Fluid Leaks	✓					

Page 1/2

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Fluid Levels/Condition	✓					
Cooling System	✓					
Power Steering	✓					
Electrical	✓					
Engine Running	✓					
Air Conditioning					✓	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓					
Transmission	✓					
Noise and Vibration	✓					
Steering and Suspension	✓					
Braking	✓					
Clutch				✓		
Instruments	✓					

General Comments

Type 'a' for ticks

