

Pre-Purchase Inspection	Classic Automobilia	
Report No	0425 250 613	Auction Lot No
	Maintenance, Modifications & Restorations	

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
	Ferrari 308 GT4	1979		14870

Rating /5 **3.0**

All values will be rounded down to the nearest 0.5

Overall Rating					Comments
1	1	1	0	0	Solid vehicle let down by poor paint and bodywork.

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				
Glass	✓					
Bodywork			✓			R/H/R guard dented, Driver's door poor shape & fit, poor boot fit.
Paintwork			✓			Paint is poor - different colours, coarse finish, faded and badly cracked.
Lamps Condition		✓				
Bumper Bars			✓			Front bar out of shape, rear bar poor.
Brightwork		✓				
Seals		✓				
Convertible Roof					✓	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓					
Seats & Belts		✓				
Floor Coverings		✓				
Headlining/Visors			✓			Sun visors baggy and filling has perished.
Trim		✓				Aged. Glove box lid hard to open.
Doors			✓			Door trims and handles pulling away.
Windows and Mirrors		✓				
Heating and Ventilation			✓			Heater control N/W. Vent controls poor.
Lights/Wipers/Washers/Horn			✓			Headlamp switch N/W & pop-up headlamps don't stay up. Washers N/W.
Other Electrical			✓			Several things N/W.
Entertainment Equipment			✓			Aerial N/S. Speaker cover missing.
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					
Corrosion	✓					
Powertrain	✓					
Exhaust		✓				
Brakes			✓			Rear brakes U/S.
Wheels & Tyres		✓				
Steering & Suspension		✓				Aged, worn and perished.
Fuel System	✓					
Fluid Leaks		✓				Engine and transmission leaking.

Page 1/2

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Fluid Levels/Condition		✓				
Cooling System		✓				Coolant tank has some corrosion inside.
Power Steering					✓	
Electrical		✓				
Engine Running	✓					
Air Conditioning			✓			Not cold. Compressor is engaged.

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓					Throttle sticks at full depression.
Transmission	✓					
Noise and Vibration			✓			Some clunks in underbody. Fan belts squeal.
Steering and Suspension		✓				
Braking			✓			Poor braking and excessive pedal travel.
Clutch	✓					
Instruments	✓					

General Comments

Type 'a' for ticks

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Key	
------------	--

Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
★ ☆ ☆ ☆ ☆	Fluid escaping and dripping	N/C	Not checked
★ ★ ☆ ☆ ☆	Vehicle requires substantial work or restoration		
★ ★ ★ ☆ ☆	Vehicle is in poor condition and in need of TLC		
★ ★ ★ ★ ☆	Vehicle is commensurate with age and useable		
★ ★ ★ ★ ★	Vehicle is in very good condition		
	Vehicle is in excellent condition		

Disclaimer	
-------------------	--

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.

This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.
