

Pre-Purchase Inspection		<div style="border: 2px solid black; padding: 5px; text-align: center;"> <b>Classic Automobilia</b>            0425 250 613            Maintenance, Modifications &amp; Restorations         </div>					Auction Lot No		
Report No	45565						Auction Lot No		
ABN: 95 933 498 716		MVRL 38236							
Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN				Rating /5	5.0
	Alfa Romeo 4C Spider	2016	9,499km	ZAR961000M172476				All values will be rounded down to the nearest 0.5	
Overall Rating			Comments						
1	1	1	1	1	Sensational vehicle.				
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments			
Presentation	✓								
Glass	✓								
Bodywork	✓								
Paintwork	✓								
Lamps Condition	✓								
Bumper Bars		✓				Front bar badly scraped on underside, has small plate added.			
Brightwork					✓				
Seals	✓								
Convertible Roof	✓								
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments			
Boot Area	✓								
Seats & Belts	✓								
Floor Coverings	✓								
Headlining/Visors	✓								
Trim	✓								
Doors	✓								
Windows and Mirrors	✓								
Heating and Ventilation			✓			Air con N/W.			
Lights/Wipers/Washers/Horn	✓								
Other Electrical	✓								
Entertainment Equipment	✓								
ABS/SRS	✓								
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments			
Structure	✓								
Corrosion	✓								
Powertrain	✓					Evidence of hydraulic mount failed.			
Exhaust	✓								
Brakes	✓								
Wheels & Tyres	✓								
Steering & Suspension	✓								
Fuel System	✓								
Fluid Leaks	✓								
Page 1/2									
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments			
Presentation	✓								
Fluid Levels/Condition	✓								
Cooling System	✓								
Power Steering					✓				
Electrical	✓								
Engine Running	✓								
Air Conditioning			✓			N/W.			
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments			
Engine Performance	✓								
Transmission	✓								
Noise and Vibration	✓								
Steering and Suspension	✓								
Braking	✓								
Clutch	✓								
Instruments	✓								
General Comments									

Type 'a' for ticks

Key									
<b>Good</b>	Operational or well presented at time of inspection	<b>U/S</b>	Unservicable						
<b>Fair</b>	Commensurate for age of vehicle but has wear and tear	<b>N/S</b>	Not secure						
<b>Repair</b>	Requires repair, replacement or refurbishment	<b>N/W</b>	Not working						
<b>Wetting</b>	Fluid escaping with the potential to drip	<b>N/A</b>	Not Applicable						
★ ☆ ☆ ☆ ☆	Fluid escaping and dripping	<b>N/C</b>	Not checked						
★ ★ ☆ ☆ ☆	Vehicle requires substantial work or restoration								
★ ★ ★ ☆ ☆	Vehicle is in poor condition and in need of TLC								
★ ★ ★ ★ ☆	Vehicle is commensurate with age and useable								
★ ★ ★ ★ ★	Vehicle is in very good condition								
	Vehicle is in excellent condition								
Disclaimer									
<p>This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.</p> <p>Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.</p> <p><b>The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.</b></p> <p>This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.</p>									
									Page 2/2