

Pre-Purchase Inspection	Classic Automobilia	
Report No	0425 250 613	Auction Lot No
	Maintenance, Modifications & Restorations	

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
45594	MGTC	1949	3,814mls	8958

Rating /5 **3.5**

All values will be rounded down to the nearest 0.5

Overall Rating					Comments
1	1	1	0.5	0	Ideal vehicle to buy drive and enjoy.

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Glass	✓					
Bodywork		✓				See below poor previous repairs.
Paintwork			✓			Body has large areas of paint and filler cracking.
Lamps Condition	✓					
Bumper Bars					✓	
Brightwork	✓					
Seals					✓	
Convertible Roof					✓	Not supplied.

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area					✓	
Seats & Belts	✓					
Floor Coverings		✓				
Headlining/Visors					✓	
Trim		✓				
Doors		✓				
Windows and Mirrors					✓	Rear view mirror poor.
Heating and Ventilation					✓	
Lights/Wipers/Washers/Horn	✓					
Other Electrical					✓	
Entertainment Equipment					✓	
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					Poorly finished timber flooring.
Corrosion	✓					
Powertrain		✓				Engine mounts perished.
Exhaust	✓					
Brakes		✓				Master cylinder push rod is set up with a dangerous kink.
Wheels & Tyres	✓					
Steering & Suspension		✓	✓			Aged, perished and worn. R/H/R spring mount on final drive has broken and has been poorly repaired.
Fuel System	✓					
Fluid Leaks		✓				Final drive leaking, engine wet, steering box wet.

Page 1/2

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Fluid Levels/Condition	✓					
Cooling System	✓					
Power Steering					✓	
Electrical	✓					
Engine Running	✓					
Air Conditioning					✓	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓					
Transmission	✓					
Noise and Vibration	✓					
Steering and Suspension			✓			Steering is binding.
Braking		✓				
Clutch	✓					
Instruments			✓			Speedo N/W.

General Comments

Type 'a' for ticks

