		_													
Pre-Purchase Inspection		-		359	ьіс		bilia								
Report No					04	25 250 613			Auction Lot No						
перон но		-	Main	topor		Modifications & Rest	ontions		Auction Lot No						
		_													
		ABN:	95 933	3 498 7	716		MVRL 3823	6							
Inspection Date				ľ	/lake/N	lodel	Year	Odometer - Mls / Km	VIN		R	ating	/5	3.0	
45565				Mess	erschm	nitt KR200		29,742mls	67917						
											All values w	vill be round	ed down to	the nearest 0.	5
		Ove	erall Ra	ting			Com	ments							
	1         1         0         0         Original vehicle in need of TLC.														
	Cood	Foir	Donoir	N/C	NI/A		Con	monto		Type 'a' for ticks					
EXTERIOR	Good		Repair	N/C	N/A		Con	iments			Тур	be a	tor ti	CKS	
Presentation Glass		<ul> <li></li> <li></li> </ul>				Crack in roof perspex.									
Bodywork		•				Some body trims damaged.									
Paintwork		•	<b>~</b>			Cracking and poor.									
amps Condition	<b>~</b>		•												
Bumper Bars					~										
Brightwork		✓													
Seals		✓													
Convertible Roof		✓				Poor fit and latching.									
NTERIOR	Good	Fair	Repair	N/C	N/A		Con	iments							
Boot Area					✓										
Seats & Belts		✓				Aged and worn. Seat slide pawl o	operation U/S.								
-loor Coverings		✓													
Headlining/Visors					✓										
īrim		✓				Aged and torn.									
Doors					✓										
Vindows and Mirrors		✓													
leating and Ventilation					✓										
.ights/Wipers/Washers/Horn	<b>~</b>														
Other Electrical					<b>~</b>										
Entertainment Equipment					<b>V</b>										
ABS/SRS		E . iu	Densir	N/0	✓		0								
UNDERBODY Structure	Good	Fair	Repair	N/C	N/A		Con	iments							
Corrosion															
Powertrain		$\checkmark$													
Exhaust		✓													
Brakes			~			Pulls left and long pedal travel.									
Wheels & Tyres		✓													
Steering & Suspension		✓				Aged.									
-uel System		✓				Poor fuel tank mounting, aged an	nd leaking.								
luid Leaks		✓													
									Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A		Con	nments							
Presentation		✓													
luid Levels/Condition				<b>~</b>											
Cooling System					✓										
Power Steering					<b>V</b>										
lectrical					<b>~</b>										
Engine Running Air Conditioning					~										
ROAD TEST	Good	Fair	Repair	N/C	▼ N/A		Con	nments							
ingine Performance							001								
Transmission			<b>~</b>			Very difficult to select gears.									
loise and Vibration		<b>~</b>	•			, a state to believe Beulo.									
teering and Suspension		• •													
Braking			~			Pulls left and poor.									
Clutch			·			Slipping.									
nstruments				•											
														·	1

					Key											
Good	Operat	ional or well pre	esented a	at time o	of inspection				U/S	Unservicable						
Fair		ensurate for age				1										
Repair		es repair, replac				1										
Watting	Fluid e	scaping with the	e potenti	al to dri	p											
	Fluid e	scaping and drip		Not checked												
$- \bigstar \bigstar \overleftrightarrow & & & & \\ & & & & & & & & & & & & & & $	★ ★ ☆ ☆ Vehicle requires substantial work or restoration Vehicle is in near condition and in nead of TLC															
* * * * *																
- × × × × × —	Vehicle	is in very good	conditio	'n												
	Vehicle	is in excellent o	condition	1							1					
					Disclaim	ier										
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																
Classic Automobilia (MVRL	8236) will n	ot be held liable	e or resp		n regards to ar purchase the v		(s) in relation	on to this r	eport or any impl	ed influence to your decision to						
The following items are no	ot included	in this inspec	ction re	port : -	Engine Com compone	-	ns, inspe	ction of C	am/Timing Bel	(s) or any internal mechanical						
This pre-purchase inspect	ion report is	not a substitute	e for a ro	adwortl	ny certificate a	nd in no	way implie	es the vehic	cle will or will not	pass a roadworthy inspection.						
										Pge 2/2						

							1			

##