

Pre-Purchase Inspection		<div style="border: 2px solid black; padding: 5px; text-align: center;"> Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations </div>				Auction Lot No	
Report No							
		ABN: 95 933 498 716		MVRL 38236			
Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN			
45582	Triumph TR4	1963	66,072mls	26460CT			
Overall Rating		Comments					
1	1	1	1	1	Very nice restoration.		

Rating /5	5.0
-----------	-----

All values will be rounded down to the nearest 0.5

EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓						
Glass	✓						
Bodywork	✓						Poor panel fit, door gaps.
Paintwork	✓						Minor chips and blemishes evident.
Lamps Condition	✓						
Bumper Bars	✓						
Brightwork	✓						
Seals	✓						
Convertible Roof	✓						

INTERIOR		Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓						
Seats & Belts	✓						
Floor Coverings	✓						
Headlining/Visors	✓						
Trim	✓						
Doors	✓						Driver's side door latch hard to open
Windows and Mirrors	✓						
Heating and Ventilation					✓		
Lights/Wipers/Washers/Horn	✓						Washers N/W.
Other Electrical	✓						
Entertainment Equipment						✓	
ABS/SRS						✓	

UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments
Structure	✓						
Corrosion	✓						
Powertrain	✓						
Exhaust	✓						
Brakes	✓						
Wheels & Tyres	✓						
Steering & Suspension	✓						
Fuel System	✓						
Fluid Leaks	✓						Engine and transmission wet.

Page 1/2

ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓						
Fluid Levels/Condition	✓						
Cooling System	✓						
Power Steering						✓	
Electrical	✓						
Engine Running	✓						
Air Conditioning						✓	

ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓						
Transmission	✓						
Noise and Vibration	✓						
Steering and Suspension	✓						
Braking	✓						
Clutch	✓						
Instruments		✓					Fuel gauge inaccurate.

General Comments	

Type 'a' for ticks

