Pre-Purchase Inspection			⊂lc	359	sic	Automobilia						
Report No					04	25 250 613 Auction Lot No						
пероп но		-	Main	tonor		Modifications & Restorations						
			L	L	lce, 1	Albertations & Restorations						
		ABN:	95 933	3 498 7	716	MVRL 38236						
Inspection Date					Make/N	odel Year Odometer - VIN			Rating /	' 5	3.0	
27/2/25					BMW	735i 2003 203,124km WBAGL42080DD80725						
27,2,23					DIVIVV	2003 203,124KIII WBAGE42000B00723			ne nearest 0.5			
		Ove	erall Ra	ting		Comments						
	1 1	1	1	0	0	Good vehicle that needs a thorough detail & some repairs.						
									_	_	_	
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments			Type 'a'	for tic	cks	
Presentation		V				Needs cleaning and detailing.						
Glass	~											
Bodywork												
Paintwork	~					Several scuffs scratches and marks.						
amps Condition		V				Front headlamps tarnished.						
Bumper Bars		✓				Have some damage and rear has paint runs.						
Brightwork					~							
Seals	~					Company of						
Convertible Roof	0000		Б	8175		Sunroof.						
NTERIOR	Good	Fair	Repair	N/C	N/A	Collect						
Boot Area		V				Soiled.						
Seats & Belts	V											
Floor Coverings			. 4			Lining angeling						
Headlining/Visors			V			Lining sagging.						
rim		V				Aged and soiled.						
Doors	V											
Vindows and Mirrors						L/H door mirror tinting N/W.						
Heating and Ventilation												
ights/Wipers/Washers/Horn	~											
Other Electrical		✓										
Entertainment Equipment ABS/SRS			_			SRS light on.						
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments						
Structure	✓	- 4	riopan	100	1071							
Corrosion												
Powertrain	•											
Exhaust	✓											
Brakes			~			Rotors worn. Brake warning lamp on.						
Wheels & Tyres			✓			Rims have gutter rash. Tyres U/S.						
Steering & Suspension	~					Ball joint boots torn.						
Fuel System	~											
Fluid Leaks			✓			Engine and transmission leaking.						
						Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments						
Presentation		~				Bonnet struts U/S.						
luid Levels/Condition	~											
Cooling System	~											
Power Steering	~											
lectrical	~											
	~											
ingine Running Air Conditioning	✓		Donoir	N/C	N/A	Comments						
ngine Running ir Conditioning	Good	Fair	Repair				1		1			
ngine Running ir Conditioning ROAD TEST		Fair	перап									
ngine Running Air Conditioning ROAD TEST Ingine Performance	Good	Fair	перап									
ringine Running Air Conditioning ROAD TEST Ingine Performance Transmission	Good	Fair	перап									
Air Conditioning ROAD TEST Engine Performance Fransmission Noise and Vibration	Good	Fair	перап									
Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension Braking	Good ✓	Fair	перап									
Engine Running Air Conditioning ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension Braking Clutch	Good ✓		nepair		•							
Air Conditioning ROAD TEST Engine Performance Fransmission Noise and Vibration Steering and Suspension Braking	Good ✓	Fair	nepair			Service light on.						

		Key							
Good Fair Repair Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear		U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked			
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia Vehicle is in poor condition Vehicle is commensurate w Vehicle is in very good cond								
	Vehicle is in excellent cond	ition Disclair	ner						
conclusively diagnosed. Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (nderbody was visually in	and any faults listed have not been spected on a vehicle hoist. ed influence to your decision to e(s) or any internal mechanica			
This pre-purchase inspection	n report is not a substitute for	a roadworthy certificate	and in no way ii	nplies t	ne vehicle will or will not	pass a roadworthy inspection.			